

JUMBO PROCESS INDICATORS
JUMBO DISPLAY INDICATORS



Specifications: -

- | | |
|----------------------------|---|
| 1) Supply | : 90-250 VAC. |
| 2) Display | : 4/6/8/10/12-inch 4 Digit seven segment high bright red display. |
| 3) Input | : mA , TH/C J &K , RTD PT 100 Type Thermocouple Sensor. |
| 4) Range | : 0 To 100 or specified by user and User Programmable |
| 5) Accuracy | : +/- 0.25 % of Span |
| 6) Alarm | : Optional High and Low alarm for temperature with buzzer. |
| 7) Calibration | : Digital Calibration using keys. |
| 8) Calibration Certificate | : Inhouse calibration certificate provided. |
| 9) Size | : As per customer requirement . |
| 10) Enclosure | : MS Powder Coated. |
| 11) Mounting | : Wall mounting or hanging. |

JAYCEE TECHNOLOGIES PVT. LTD.

An ISO 9001-2008 C E Certified Company
Shed No. 7, Nanekar Industries Building, Survey No. 79/2,
Dangat Industrial Estate, Shivane, Pune - 411 023, India
Contact No. : 9371068669/8554982251